

CASPIR Aircraft Accident Cards

Serial: 11525

Title: Avro Anson Mk. II serial:11525 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1944-March-10. Anson II s/n 11525. This accident involved 1 person. Carlson WD

Keywords: RCAFAnson II,11525,19 SFTS,19 Service Flying Training School,Aerodrome,1944-March-10,CarlsonRCAF L20

Created: 1944-03-10

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#11525>

61 60 59 58 57 56 55 54 53 52 51 50 49 48 47 46 45 44 43 42 41 40 39 38 37 36 35 34 33 32 31

ACCIDENT CLASSIFICATION

UNIT 19 S.F.T.S.
Vulcan, Alta.

COM.

4

PLACE

M.A.

DATE 10-3-44

TIME 0815

H.Q. FILE 1100-115-25

A/C TYPE

ANSON II

NO.

11525

CRASH CAT.

"D"

S.E.

M.E.

DAY

NIGHT

x

x

COMMAND

PERSONNEL

RANK

NUMBER

DUTY

INJURIES

SIGNAL

Carlson, W.D.

LAC

R185760

OC

Uninj.

NO.

A98

DATE

10-3-44

D 14 (REVISED)

NO.

CHECKED

MONTH

FORCED LANDING
TAXYING
LANDING
TAKE-OFF

N I F A

#11

STAGE OF FLIGHT

FLIGHT
STATRY
FATAL
INJURY

ENGINE

ENGINE NUMBER (S)

HOURS FLOWN BY PILOTS

L6MB

P.14170/25481 NIL
S.14171/25482 NIL

INST.

NIGHT

ON TYPE

TOTAL

SOLO

DUAL

SOLO

DUAL

TYPE OF A/C
TYPE OF UNIT
CATEGORY

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61

PURPOSE OF FLIGHT:

Aero engine mechanic detailed to start engine.

TECHNICAL OFFICER'S REPORT:

NIL.

NATURE OF ACCIDENT:

Aero Engine Mechanic detailed to start engines. When engines were started, U/C collapsed breaking propellers.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

REMARKS OF UNIT C.O. Since there are Flight Orders, issued by Maintenance Wing, to the ground crew covering this case explicitly, disciplinary action should provide a suitable reminder.

CLASSIFICATION:

57. Miscellaneous.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Airman being charged.