

ACCIDENT CLASSIFICATION

UNIT 1 O.T.U. Bagotville		COM. E	PLACE M.A.		DATE 3-5-44	TIME 1655 GMT	
A/C TYPE HURRICANE XITA		NO. 1379		CRASH CAT. "C"	S.E. X	M.E.	DAY X
PERSONNEL		RANK	NUMBER	DUTY	INJURIES		SIGNAL
FERHAM, J.G. AUS		SGT	430692	P	Uninj.		No. A381
							DATE 3-5
							D 14 (REVISED)
							No. 3
							CHECKED <input checked="" type="checkbox"/>
							#5
ENGINE	ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS				
Merlin	19407/A3590 serious		INST.	NIGHT	ON TYPE		TOTAL
					SOLO	DUAL	SOLO
			41	18	36	-	115
							131

COMMAND
MONTH
STAGE OF FLIGHT

7
4
2
1
7
4
2
1
FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STATVY
FATAL
INJ.
INJURY
380
5
M

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Low flying and aerobatics.

NATURE OF ACCIDENT:

W/D collapsed after landing.

A/c swung on landing

TECHNICAL OFFICER'S REPORT:

LS/PSS/US

NIL

CAUSE OF COLLAPSE NOT DETERMINED.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~61. Swinging on landing.~~

5 W/c failure

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

NIL