

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62

ACCIDENT CLASSIFICATION

UNIT # 6 E.F.T.S. Prince Albert		COM. 2	PLACE 20 miles N.E. OF M.A.		DATE 9-5-44	TIME 1625	
A/C TYPE Tiger Moth		No.	CRASH CAT. F/L		H.Q. FILE 1100-38-80	S.E. x	
		3880			M.E.	DAY x	
						NIGHT	
PERSONNEL		RANK	NUMBER	DUTY	INJURIES		
Leathers, R.G.		LAC	1806914	pp	Nil		
					SIGNAL		
					No.	DATE	
					No sig.		
					D 14 (REVISED)		
					No.	CHECKED	
					2		
					# 8		
ENGINE		ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS			
Gypsy Major		7446/87267 Nil		ON TYPE		TOTAL	
				INST.	NIGHT	SOLO	DUAL
				-	-	6	22
						6	22

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

7  
4  
2  
1  
7  
4  
2  
1  
Forced Landing  
TAXIING  
LANDING  
TAKE-OFF  
FLIGHT  
STATRY  
FATAL  
INJURY  
3RD  
5  
4

ACCIDENT CLASSIFICATION

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62



) PURPOSE OF FLIGHT:  
Solo practice. Seq. 14-16-17.

TECHNICAL OFFICER'S REPORT:  
Nil

) NATURE OF ACCIDENT:  
Pupil landed in field due to low visibility in line squall.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:  
FINDINGS: SUMMARY No.

)

)

)

)

)

)

) CLASSIFICATION:  
58. Precautionary landing.

)

)

) SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:  
Nil

