

ACCIDENT CLASSIFICATION									
UNIT # 9 BG.S. Mont Joli		COM. 3	PLACE 2 miles W of M.A.		DATE 21-7-44	TIME 1645			
A/C TYPE			No.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT	
BATTLE			7374	"C"	x		x		
PERSONNEL		RANK	NUMBER	DUTY	INJURIES		SIGNAL		
Munro, W.D.		Sgt	R176869	P	Uninj.		No.	DATE	
							N95	21-7	
							D 14 (REVISED)		
							No.	CHECKED	
							4		
							# 5		
ENGINE		ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS					
Merlin III		118638/2925		SLIGHTLY		ON TYPE		TOTAL	
				INST.	NIGHT	DUAL	SOLO	DUAL	SOLO
				45	40	7	100	151	426
ACCIDENT CLASSIFICATION									

PURPOSE OF FLIGHT:

Scheduled target a/c on camera gun exercises.

NATURE OF ACCIDENT:

Engine running rough and loss of power, the pilot had to force land a/c in the nearest and best suitable field with wheels retracted.

TECHNICAL OFFICER'S REPORT:

Engine failure in the air. - probable burnt flame traps.

FB/ADP/ES/FT/D/1/U01K/B

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

17. Forced landing.

SECONDARY OR CONTRIBUTORY FACTORS:

26. Engine trouble-Accident.

ACTION TAKEN:

Nil.