



PURPOSE OF FLIGHT:

Taxiing prior to practice routine training flight. Nil

TECHNICAL OFFICER'S REPORT:

MULTI  
TCA/PCT/KCI  
MA/KA

NATURE OF ACCIDENT:

Pilot of A/C 7519 attempted to taxi in a congested area on tarmac and collided with a parked aircraft. (FP818)  
Surface of ground was slippery and congestion due to high snow banks.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

9. Collisions.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil