

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62

ACCIDENT CLASSIFICATION

UNIT 124 Ferry Sqdn. COM. St. Hubert, P.Q. 1		PLACE RCAF Stn. Trenton, Ontario.	DATE 23-4-45	TIME 1400
A/C TYPE HARVARD II (124 F.S.) ANSON V (14 SFTS)		NO. 2959 - P 12111	H.Q. FILE 1100-121-11	
		CRASH CAT. "B" "C"	S.E. X	M.E. X
			DAY X	NIGHT

COMMAND
MONTH
STAGE OF FLIGHT

PERSONNEL	CAN.	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
PALMER, M.S.	(124 F.S.)	F/O	J37337	P.	Uninj.	NO.	DATE
BROWN, J.H.	(14 SFTS)	F/L	J9752	P.	Uninj.	T.213	24-4
McMILLAN, R.,		S/L	C4382	Pass.	Uninj.	D 14 (REVISED)	
GARDINER D.,	(RCNVR)	Lt.		Pass.		NO.	CHECKED
SHEPPIT, J.,		Sgt.	R56961	Pass.			

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				DUAL	SOLO	DUAL	SOLO
P. & W. S3H1	4420/7561 Nil P.JR210845/14445 Nil						
P. & W. Wasp Jr.	S.JR210837/14437 Nil	189	295	2.	12	146	1791
Information not at this unit.							

ACCIDENT CLASSIFICATION

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62

PURPOSE OF FLIGHT:

124 F.S.- Ferrying A/C
14 S.F T.S.- Engineering duties.

NATURE OF ACCIDENT:

Pilot collided with Anson 12111
whilst taxiing. Vision was
obstructed.

TECHNICAL OFFICER'S REPORT:

Nil

TCA/PCL
TCA/XA

MULT ✓

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY NO.

CLASSIFICATION:

9. Collisions.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Log Book Endorsed.

Pending