

## CASPIR Aircraft Accident Cards

---

**Serial:** FP290

**Title:** Consolidated Canso Mk. IB serial:FP290 Accident Card

**Author:** Royal Canadian Air Force (RCAF)

**Subject:** This accident involved 1 aircraft on 1943-March-04. Catalina IB s/n FP290.

**Keywords:** RCAF Catalina IB, FP290, 117 Sqn, 117 Squadron, Launching Slipway, 1943-March-04, RCAF L20

**Created:** 1943-03-04

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000357#FP290>



DUTY ON WHICH ENGAGED:

**N.A.**

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

**D-14**

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

**Whilst towing A/C tractor skidded  
on icy slope and collided with  
A/C.**

DATE:

COMPOSITION:

RECOMMENDATIONS:

**Sufficient supply of calcium chloride to be kept  
within the Unit at all times during freezing weather.**

PRIMARY CAUSE:

**1. Bad surface of aerodrome.**

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

**NIL.**

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

**2. Hitting obstructions.**

RECORDED BY \_\_\_\_\_

DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_

DATE \_\_\_\_\_